

Method 303 Inspections By Veolia Water NA

Year: 2016 Month: March

Reports Submitted

US Steel - Clairton

Monitoring Report	<input checked="" type="checkbox"/>
Topside Observations	<input checked="" type="checkbox"/>
Door Observations	<input checked="" type="checkbox"/>
Charging Observations	<input checked="" type="checkbox"/>
High Frequency Door Leaking Report	<input checked="" type="checkbox"/>
High Frequency Offtake Leaking Report	<input checked="" type="checkbox"/>
Daily Emissions Summary	<input checked="" type="checkbox"/>

USS-CI Battery	NESHAPS - Exceedances of Stds.				State Implementation Plan - Exceedance of Standards											
	Offtakes 2.5%	Lids 0.4%	Doors 3.3%	Charging 12 sec.	OFFTAKES			CHARGING PORTS (LIDS)			DOORS			CHARGING		
					Insp.	Viols.	Std.	Insp.	Viols.	Std.	Insp.	Viols.	Std.	Insp.	Viols.	Std.
1	0	0	0	0	31	0	5%	31	0	2%	31	1	8%	31	0	75 sec/4 charges
2	0	0	0	0	31	0	5%	31	0	2%	31	0	8%	31	0	75/4
3	0	0	0	0	31	0	5%	31	0	2%	31	1	8%	31	0	75/4
13	0	0	0	0	31	0	4%	31	0	1%	31	0	5%	31	0	55/5
14	0	0	0	0	31	0	4%	31	0	1%	31	0	5%	31	0	55/5
15	0	0	0	0	31	0	4%	31	0	1%	31	0	5%	31	0	55/5
19	0	0	0	0	31	0	5%	31	0	2%	31	0	8%	31	0	75/4
20	0	0	0	0	31	1	4%	31	0	1%	31	0	5%	31	0	55/5
B	0	0	0 ¹	0	31	0	4%	31	0	1%	31	0	5%	31	1	55/5
C	0 ²	0 ³	0 ⁴	0	31	0	3%	31	0	0.6%	31	0	3%	31	0	55/5

¹ 4.0% Door Std.

² 1.5% Offtake Std.

³ 0.15% Lid Std.

⁴ 2.0% Door Std.

USS CI Summary Report Received:

Apr 11, 2016

USS CI Invoice Received:

Apr 27, 2016